

Historic American Buildings Survey

HABS
ID.
30-SAL.
1-

Index to Photographs

Leesburg Townsite
Napias Creek
Salmon Vicinity
Lemhi County
Idaho

HABS No. ID-106

NOTE: Photographs were taken Lon Johnson, photographer, June 1992

- ID-106-1 GENERAL VIEW OF LEESBURG TOWNSITE, LOOKING EAST
- ID-106-2 GENERAL VIEW OF LEESBURG TOWNSITE, LOOKING EAST-NORTHEAST
- ID-106-3 GENERAL VIEW OF LEESBURG TOWNSITE, LOOKING NORTHEAST
- ID-106-4 GENERAL VIEW OF LEESBURG TOWNSITE, LOOKING WEST
- ID-106-5 GENERAL VIEW OF LEESBURG TOWNSITE, LOOKING SOUTH
- ID-106-6 GENERAL VIEW OF LEESBURG TOWNSITE, LOOKING SOUTHEAST
- ID-106-7 GENERAL VIEW OF LEESBURG TOWNSITE, LOOKING SOUTHWEST
- ID-106-8 OVERVIEW OF THE TOWNSITE, LOOKING WEST
Photographic copy of historic photograph. No date. Original print is located in Lemhi County Historical Museum, Salmon, Idaho. Photographer is unknown.
- ID-106-9 OVERVIEW OF THE TOWNSITE, LOOKING EAST
Photographic copy of historic photograph. Taken prior to 1929. Original print is located in Lemhi County Historical Museum, Salmon, Idaho. Photographer is unknown.
- ID-106-10 VIEW OF BUILDINGS ON NORTH SIDE OF MAIN STREET, LOOKING NORTHEAST
Photographic copy of historic photograph. Taken prior to 1929. Original print is located in Lemhi County Historical Museum, Salmon, Idaho. Photographer is unknown.
- ID-106-11 VIEW OF STABLE, STAGE OFFICE, AND RUIN (Features 2, 3, and 4). EAST ELEVATION. LOOKING WEST
- ID-106-12 3/4 VIEW OF STABLE, STAGE OFFICE, AND RUIN (Features 2, 3, and 4), SHOWING DUGOUT RUIN IN FOREGROUND, LOOKING SOUTHWEST

ID-106-13 VIEW SHOWING NORTH AND EAST ELEVATIONS OF FEATURES 22 AND 23,
LOOKING SOUTHWEST